

Bags that become blinded reduce airflow and could potentially harm the vacuum producer due to restricted airflow and will result in overheating.

