

REPLACEMENT BULLETIN

September 22, 2022

Compact Top Brush

Main Sub-Assembly Replacement




Do NOT Unpack Until Ready For Installation
Use the Lift Points When Unpacking Main Sub-Assembly

SUMMARY

The image below shows the Compact Top Brush Main Sub-Assembly Lift Points when unpacking it from the shipping crate.

 **IMPORTANT:** Do NOT unpack until ready for installation. Main Sub-Assembly Replacement Part # 20018771.



DANGER: Always Shutoff All Power to Conveyor and/or Equipment Before Starting Any Install, Maintenance, Service or Repairs. Failure to do this may result in personal injury, death, and/or dismemberment.

